

Shop Work Safety

- ✓ **Keep all tools in good working order.**
- ✓ **Put tools away when not in use.**
- ✓ **Know the correct method of jump-starting machinery.**
- ✓ **Always block jacked-up equipment before working on, under, or around.**
- ✓ **Always mark containers with their contents.**
- ✓ **Use eye protection when appropriate.**
- ✓ **Use sockets correctly; using cheater bars or excessive force can break sockets and cause injury.**
- ✓ **When climbing/descending ladders use a rope to carry tools and equipment.**
- ✓ **Do not keep combustible material near the welder or where welding.**
- ✓ **Do not use the welder or cutting torches without proper training.**
- ✓ **Ensure adequate ventilation when welding, running engines, using chemicals, storing chemicals/fuels, etc.**
- ✓ **Keep floor and bench areas clean and dry.**

